## Quick die change system for FINN-POWER crimping machines

Additional accessories available for P type tabletop series of crimping machines are quick die change systems consisting of quick change tool base (QC-Tool Base) with storage place for dies (photo 1) or die set rack (photo 2) and magnetic quick change tool (QC-Tool) that allows to change out a set of dies at once (photo 3). Crimping machines of FP series are supplied with the QC system as a standard.




photo 1




photo 2



photo 3

| code | description |
|---|---|
| FP-QCT-20X | tool base for P20X with magnetic quick change tool |
| FP-QCT-20 | tool base for P20 / P21 with magnetic quick change tool |
| FP-RACK-20 | die set rack type 20 with magnetic quick change tool |
| FP-RACK-32 | die set rack type 32 with magnetic quick change tool |
| FP-QCT-51 | tool base for P51 / P60 with magnetic quick change tool |
| FP-QCTN-20 | tool base for 20 MS(UC) with magnetic quick change tool |
| FP-QCTN-32 | tool base for 32 MS(UC) with magnetic quick change tool |

## Control options of FINN-POWER crimping machines



### MS(N)

New control solution available in new generation of crimping machines P20 MSN and P32 MSN replacing MS and IS control. Apart from two button operation (crimping - opening) the crimping machine can be operated with foot pedal (option), using automatic backstop (option) or in semi-automatic mode. Equipped with motor stand-by function.